



JON M. HUNTSMAN, JR.  
Governor


GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
**Date:**

Reviewed: 

<b>Mine Name:</b> : Bullseye #1	<b>Permit Number:</b> S/023/0031
<b>Operator Name:</b> Edwin Lister	<b>Inspection Date:</b> May 17, 2011
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 2:40 – 3:10 PM
<b>Other Participants:</b> None	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

This was a routine inspection.

**Inspection Summary:**

The current bond is for \$7,000.00. On October 27, 2009, the Division sent the Operator a letter requiring a bond increase of either \$11,700.00 for three years or \$12,000.00 for five years. The Operator has not responded. The Operator has until August 1, 2011 to post additional bond or the Division will issue a cessation order.

The site appears stable. There is limited amount of equipment on site, part of a grizzly. No erosion was noticed.

The back part of the site appears to be backfilled and graded but no topsoil was placed.

**Conclusions and Recommendations:**

The Division will issue a cessation order requiring the Operator to post adequate bond or reclaim the site if additional bond is not post by August 1, 2011.



**Inspector's Signature**

*Wayne Watson*

WHW:

cc: (OPERATOR)

Jerry Mansfield

O:\M023-Juab\S0230031-Bullseye\inspections\insp-05172011.doc





Entrance sign



Active pit





Backfilled area no topsoil



Backfilled and graded area no topsoil